# Oil Field Environmental Incident Summary

**Responsible Party:** Rud Transportation **Well Operator:** OXY USA INC.

Well Name: FRANCIS BROWNELL 1-16-21H-143-98

Field Name: LITTLE KNIFE Well File #: 26090

Date Incident:1/9/2014Time Incident:1000Facility ID Number:County:BILLINGSTwp:143Rng:98Sec:16Qtr:

Location Description:

Submitted By: Dustin Tescher Received By:

Contact Person: Dustin Tescher

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MilesDistance Nearest Water Well:0.5 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No **Units** Recovered Spilled Units Followup **Units** Oil 0 barrels 0 barrels **Brine** barrels barrels 0 barrels Other barrels 0 barrels

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 1/21/2016 Clean Up Concluded: 4/22/2014

Risk Evaluation:

Areal Extent:

## Potential Environmental Impacts:

Contaminated surface material inside of containment berm.

# Action Taken or Planned:

The well was shut down to stop the release and trucks were called to lower the fluid level in the tanks and recover and standing fluid from the containment berm.

Wastes Disposal Location: Cabernet SWD

Agencies Involved:

#### **Updates**

Date: 1/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

Release, due to tank overflow, remained on location within the diking, according to the report. NDIC retains oversight.